

Proposed Siding Change for
The Studio: A Hair Salon
6300 W Broadway
McCordsville, IN 46055

Reason: **Degradation and poor insulation of current siding**

Product to be used: **Hardie Board Fiber Cement Lap Siding and Trim - 7" Reveal - Cedarmill**

Area: **All areas currently covered with existing siding and trim**

Color: **Behr "White"**



Product Example



Example of color, horizontal application (bottom) and cedar accents that provide the general "look".

Photos of Current Siding



Additional Design Elements

10" natural cedar posts to be added to the front of the building as seen in this rendering.




A post will also be added at the back of the building under the awning with a "Y" support as seen in the example photo.



(Additional Design Elements Cont'd)

Cedar plank to be applied to the sides of the awnings in both the front and the back of the building as seen in the example photo.



Apply cedar accent panels to the bump out areas at the top of the walls on both the west and east sides of the building as seen in the example photo.

Paint the chimney black.



(More)

All window trim black and in this size and style.

